

ENViñ

SCIENTIFIC LIMITED

SPARES

Sensors only replacements are available for this product. The 2011 series of Pilot Gas Alarms now have a Socket arrangement for the sensor which is located inside the black sensor housing. Should the boat undergo any maintenance work it is recommended that the sensor(s)

are removed from their socket and placed into a clean seal-able plastic wallet to avoid contamination.

Part Number: 201115 Sensor only

Part Number: 201115 - 3.5 Sensor complete with cable 3.5mtrs

Part Number: 201115 - C Sensor complete with cable 150mm plus connector block

Any queries please do not hesitate to contact us.

e-mail: info@envinsci.co.uk | web: www.envinsci.co.uk | phone: +44 (0)1829 771 792

ENViñ

SCIENTIFIC LIMITED

Sensor Wiring

The wiring colours may vary from the original cable fitted. The current wiring information is shown in the table below.

Colour	Mini	Twin & GMS
Red	3	3 & 6
Black	4	5 & 8
Yellow	5	4 & 7

e-mail: info@envinsci.co.uk | web: www.envinsci.co.uk | phone: +44 (0)1829 771 792